



RELEASE NOTE

AT Version X.51a

Revision: 001
Date: December 2005



wavecom[®]
Make it wireless



AT Version **X.51a** Release Note

651a09gg.v13
351a09gm.v13

Reference : **WM_DEV_OAT_DVD_009**

Version : **001**

Date : **December 09th 2005**

| Level | Date | History of the evolution | |
|--------------|-----------------------|---------------------------------|--|
| 001 | December 09th 2005 | Creation | |

Copyright

This manual is copyrighted by WAVECOM with all rights reserved. No part of this manual may be reproduced in any form without the prior written permission of WAVECOM.

No patent liability is assumed with respect to the use of the information contained herein.

Trademarks


[®], WAVECOM[®], WISMO[®], Open AT[®] and certain other trademarks and logos appearing on this document, are filed or registered trademarks of Wavecom S.A. in France or in other countries. All other company and/or product names mentioned may be filed or registered trademarks of their respective owners.

Table of Contents

| | |
|---|-----------|
| 1 INTRODUCTION | 6 |
| 1.1 SCOPE OF THIS DOCUMENT | 6 |
| 1.2 AUDIENCE FOR THIS DOCUMENT | 6 |
| 1.3 RELEASE FEATURE LIST | 6 |
| 1.3.1 MAIN FEATURES REMINDER | 6 |
| 1.3.2 NEW FEATURES / EVOLUTIONS | 6 |
| 1.4 DEDICATED VERSIONS FOR SPECIFIC MARKETS | 6 |
| 1.4.1 NEW PRODUCT INTRODUCTION | 6 |
| 1.4.2 DEDICATED VERSION | 7 |
| 1.4.3 STORAGE & MARKING | 7 |
| 1.4.4 AVAILABILITY | 7 |
| 1.4.5 WARNING | 7 |
| 1.4.6 SOFTWARE BEHAVIOR | 7 |
| 2 RELATED DOCUMENTS | 8 |
| 3 ABBREVIATIONS AND DEFINITIONS | 9 |
| 4 HARDWARE COMPATIBILITY | 10 |
| 4.1 MODULE COMPATIBILITY | 10 |
| 5 SOFTWARE RELEASE DESCRIPTION | 10 |
| 5.1 RELEASE IDENTIFICATION | 10 |
| 5.2 RELEASED FILES & DOWNLOAD PROCESSES | 10 |
| 5.2.1 X-MODEM DOWNLOAD MODE | 11 |
| 5.2.1.1 X-Modem configuration required for download | 11 |
| 5.2.1.2 Common Files required for download | 11 |
| 5.2.1.3 Download procedure | 11 |
| 5.2.1.4 Specific GPS Files (only for Q2501B series) | 12 |
| 5.2.2 DWLWIN DOWNLOAD MODE | 12 |
| 5.2.2.1 DWLWin configuration required for download | 12 |
| 5.2.2.2 Common Files required for download | 12 |

| | | |
|-------------------------------|---|-----------|
| 5.2.2.3 | Download procedure | 12 |
| 5.2.2.4 | Specific GPS Files (only for Q2501B series) | 12 |
| 5.3 | SOFTWARE TOOLS VERSION | 13 |
| 6 SOFTWARE DESCRIPTION | | 14 |
| 6.1 | VALIDATED CORRECTIONS/IMPROVEMENT | 14 |
| 6.2 | INTEGRATED BUT NOT VALIDATED CORRECTIONS/IMPROVEMENT | 16 |
| 6.3 | SPECIFICITIES VERSUS PREVIOUS OFFICIAL RELEASE ON THE BRANCH | 16 |
| 6.4 | CERTIFICATION COMPLIANCE | 16 |
| 6.5 | ADDITIONAL INFORMATION / RESTRICTIONS | 16 |
| 6.5.1 | COMMON TO ALL MODULES | 16 |
| 6.5.2 | SPECIFIC TO A MEMORIES | 17 |
| 6.5.3 | SPECIFIC TO Q2501B MODULE | 17 |
| 6.5.4 | SPECIFIC TO M1306B MODEM | 18 |

1 Introduction

1.1 Scope of this document

The scope of this document is the **X.51a** AT software release description for WISMO Quik series **Q2400A**, **Q2406x**, **Q2426B** and **Q2501B**.

1.2 Audience for this document

This Release note may be distributed to all direct and indirect customers and will be posted on the corporate web site under the Support/Private area.

1.3 Release Feature List

1.3.1 Main Features Reminder

| Features list for AT | SW version | |
|--|------------|------|
| | 351a | 651a |
| Multiple UART management | X | (*) |
| Extended SMS Storage: up to 99 in Flash | X | X |
| Extended Phone Book Management (Name, 5 numbers, address, e-mail, group) | X | X |
| Low Power consumption for the module with disconnected mode (Radio and protocol stack off: but Open AT® Application running) | X | X |
| Interruption PIN Management | X | X |
| GPS Management (Q2501B only) | | X |
| Agenda management | X | X |
| Extended characters | X | X |
| SIM Speed Enhancement default activation | X | X |

(*): Refer to chapter 6.5.3.

1.3.2 New Features / Evolutions

None.

1.4 Dedicated versions for Specific Markets

1.4.1 New product introduction

As per specific market requirements, additional "countries dedicated" version of module has been launched.

1.4.2 Dedicated version

As these products are tailored for the dedicated countries, they are locked not to work on any other network but the selected country's available carriers. These products will not be compatible with the former SW versions on the branch (refer to 0). Obviously Wavecom will perform maintenance on these product in the same way as it is done on other products.

1.4.3 Storage & Marking

For countries dedicated versions, in the Product Code file, the SW Configuration of this version includes the mention "CCx", x depending on the country.

This SW configuration will only appear on the pizza box. A special attention is required to manage the storage, as this SW configuration is the only way to distinguish the product.

1.4.4 Availability

SW versions available on the Wavecom web site are only for not dedicated products.

In order to obtain Software version for updating the products dedicated to specific countries, contact your Wavecom technical support.

1.4.5 Warning

Standard X.51a software not tuned for dedicated countries must not be used on modules that are dedicated to a specific country, as it is not compatible. In this case, the message BAD SOFTWARE is displayed (refer to the AT Command Interface Guide for more information on this message). This can be undone by re-downloading a compatible version.

1.4.6 Software Behavior

Specific country lock feature aims at locking a module use to a pre-determined list of countries.

⇒ The use of module for not allowed countries is forbidden. In this case, the message "**SIM NOT ALLOWED FOR THIS MODULE**" is sent, the module resets and AT SIM commands are then no more available.

⇒ The module upgrade by using a specific country lock version is not reversible. Effectively, all modules upgraded by using such a version won't be allowed to use previous software version. In this case, a message "**BAD SOFTWARE**" will be displayed.

2 RELATED DOCUMENTS

| | | |
|-----|--|--|
| [1] | AT Commands Interface Guide for revision X51a | WM_ASW_OAT_UGD_00016-006 |
|-----|--|--|

| | | |
|-----|-----------------------------------|--|
| [2] | Hands free audio application note | WM_ASW_OAT_APN_014-001 |
|-----|-----------------------------------|--|

3 ABBREVIATIONS AND DEFINITIONS

| | | |
|-----|---|-------------------------|
| IFS | : | Interface Specification |
| LLC | : | Low Layer Compatibility |
| STK | : | SIM Toolkit |
| UGD | : | User Guide |
| WM | : | Wavecom |
| DF | : | Design Feature |

4 Hardware Compatibility

4.1 Module Compatibility

| X51a Software version | Module Compatibility List |
|-----------------------|--------------------------------------|
| 6.51a | Q2406A Q2406B Q2426B Q2501B |
| 3.51a | Q2400A |

5 Software release description

5.1 Release identification

| WISMO Quik – Q24X6X, Q2400A and Q2501B - Series | | | |
|---|---------------------|---------------|---------------------|
| Date of generation | November 30, 2005 | | |
| Software identification | 651a09gg.Q2406A | 16/2 Mbits | GPRS+Open AT@ |
| | 651a09gg.Q2406B | 32/4 Mbits | GPRS+Open AT@ |
| | 651a09gg.Q2426B | 32/4 Mbits | GPRS+Open AT@ |
| | 651a09gg.Q2501B | 32/4 Mbits | GPRS+Open AT@ + GPS |
| | 351a09gm.Q2400A | 16/2 Mbits | GSM only + Open AT@ |
| IMEISV | 19 | | |
| Checksum | 6.51a | 0x9F D8 68 96 | |
| | 3.51a | 0x9F D8 6B 92 | |
| Flash type | 16/2 Mbits (type A) | | |
| | 32/4 Mbits (type B) | | |
| Open AT@ version | V3.03 | | |
| Xmodem downloader | V2.14 | | |
| Previous Official Release on the Branch | 6.51 (6.51a) | | |
| | 3.51 (3.51a) | | |

5.2 Released Files & Download Processes

This section describes the files that need to be downloaded on the module with DwlWin tool or with a HyperTerminal software.

5.2.1 X-Modem download mode

5.2.1.1 X-Modem configuration required for download

In order to download the FW by using the X-Modem protocol, the following configurations and conditions have to be set:

- Create an Hyper Terminal connection on COM port with following parameters:
 - *Bit/Second* **115200**
 - *Data Bit* **8**
 - *Parity* **None**
 - *Bit Stop* **1**
 - *Flow Control* **Hardware**
- A version of AT software must be already downloaded on the module

5.2.1.2 Common Files required for download

The file to download depends on the HW platform. This file has the following name:

- **X51a_full_<Module_Type>.dwl**

The content of this file is the following:

- X.51a binary version,
- Common E2P configuration (w.dwl file),
- E2P configuration specific to <Module_Type> module.

Ex: 651a_q2406b.dwl is the file to download on a module Q2406B.

5.2.1.3 Download procedure

The following procedure has to be performed in order to download the FW in the module:

- Connect the Starter Kit on this COM port and start the module.
- Enter "at<CR>" on the Hyper Terminal windows. Module has to answer:
"OK"
- Check the current downloader (dwl) on the module side. It must be the same or compatible to the embedded one in the new binary (see the Xmodem downloader version in the table paragraph 5.1).

NB: To recall the current dwl version, enter "at+wdwl?<CR>" on the Hyper terminal. The module answers:

" +WDWL: V<downloader version> "

If existing downloader is not the good one, the new downloader has to be reloaded first. In order to download it, use the following process and select "dwl.dwl" as file to download. When download is completed and the module has been reset, repeat the following procedure to download the new AT binary.

- Enter "at+wdwl<CR>" to start the download. Module has to answer:
" +WDWL: 0
||||| "
- Enter menu "Transfer/Send a file"
- Select protocol: "1k Xmodem"

- Select the *dwl* file to download.
- Validate so that the download starts.
- When new characters "█" are received, the download is finished.
- Reset the module by using the command "*AT+CFUN=1*" and wait for the "OK" answer.

5.2.1.4 Specific GPS Files (only for Q2501B series)

Not applicable.

5.2.2 DwlWin download mode

5.2.2.1 DWLWin configuration required for download

Before launching the download process, the DWLWin tool has to be configured as following:

- Select CPU type field according to the module series:
 - **WISMO 2-3** For Q24 series module
 - **Q2501** For Q2501 modules
- Select "Erase objects" and "Erase Customization Files" options

5.2.2.2 Common Files required for download

The E2P parameters to download depend on the HW platform. For this reason, two files must be downloaded for E2P parameters:

- **pro-dwl.wpb** (Binary)
- **w.e2p** (Generic E2P file)
- **<Module><FlashType>.e2p** (module specific E2P file)
For example: 'q2406b.e2p' for Q2406 module with flash type B (32/4)

Warning: All these files must be downloaded at the same time.

Note: the *custo_AT.CUS* file provided with previous X50a firmware is no more provided since X51 firmware. The content of this file is now directly included in the binary file.

5.2.2.3 Download procedure

Refer to DWLWin Help provided in the DWLWin tool.

5.2.2.4 Specific GPS Files (only for Q2501B series)

The GPS following file must be downloaded for the Q2501B module version:

- **<CodeSoft>_300-gps.wpb** (GPS binary file)

5.3 Software Tools Version

This section gives the last Wavecom tools versions.

| S/W Tools Name | Version |
|------------------------------|----------------------|
| DwlWin Downloader | v3.3.9.1 |
| Target Monitoring Tool (TMT) | V2.7.5.0 |
| TMT Workspace | B51i09gx.v13_64k.wks |

6 Software Description

The following table shows the feature availability depending on the SW version.

| | 3.51a | 6.51a |
|---------------|-------|---------------|
| GPRS Class 10 | No | Yes |
| Open AT® | Yes | Yes |
| TCP/IP | No | Yes |
| GPS | No | Yes on Q2501B |

The *Severity* values have the following meaning :

- 1 : Critical
- 2 : Major
- 3 : Minor
- 4 : Cosmetic

6.1 Validated Corrections/Improvement

This section gives the list of all corrections or improvements integrated in the X.51a version from the X.51 version.

| Id | Description (What / When) | Impacted Domain | Impacted Sub Domain | Severity* |
|-------|--|-----------------|---------------------|-----------|
| 28002 | During the TC 27.22.4.15 GCF test, the module resets after a Provide local information (MNR) proactive command | AT | STK | 1 |
| 28877 | TC 46.1.2.2.4.3 failed : GCF 3.18.0 [Cat. A] : Reset of the MS at step 11. | GPRS | OTHER | 1 |
| 28910 | TC 46.1.2.2.4.3 failed : GCF 3.18.0 [Cat. A] : Reset of the MS at step 11. | GPRS | OTHER | 1 |
| 29068 | The module resets when a call is made with SIM cards having incorrect LND entries | AT | PHONEBOOK | 1 |
| 29217 | When the E2P mirror is restored, some settings are not updated. This results in incorrect settings. | AT | OTHER | 1 |
| 29241 | When activating modem powerless mode with command AT+WBHV=1,1, modem turns also into "response mode on a call : display of OK just after +WIND : 5,x indication". This results in the reception of 2 consecutive OK. | AT | OTHER | 1 |
| 29242 | Activation of Low consumption through command at+wbhv=1,2 causes OK then an ERROR code although the activation is taken into account. | AT | OTHER | 1 |
| 29261 | When an Open AT application is running, if the external application uses the AT+CCED=0,1 command, the module resets. | AT | OTHER | 1 |
| 29378 | On Q2501B module, when setting GPIO3 as an input, it is not available for reading purpose. | DEVICE | ADC/BAT | 1 |
| 29452 | Reset when EF_CBMI present in SIM card and AT+CSCB=1 sent | AT | SMS | 1 |
| 29811 | Reset may occur on specific networks after a location update if a handover occurred during this procedure and SI5 was not received on the target cell before location update completion. | GSM | RR | 1 |
| 29824 | If a SIM card has more than 20 "Replace type" SMS, the module | AT | SMS | 1 |

| | | | | |
|--|---|--------|---------|---|
| | resets systematically during a SMS reading (+CMGR command). | | | |
| 29871 | TC 21.3.2 failed : GCF 3.18.0 [Cat. B] : OPEN_LOOP_CMD with Ack not sent at the end of the test. | GSM | OTHER | 1 |
| 29945 | When battery charging is used (command AT+WBCM), ADC values are not updated any more with the command AT+ADC?. | DEVICE | N/A | 1 |
| 30155 | Battery charging could cause a damage on the battery, when charger stays plugged for a while after the end of charge. | DEVICE | ADC/BAT | 1 |
| 30209 | Default value for the number of dictionary entries is set to 2048 (command AT+DS). This value may cause outgoing DATA calls to fail. The default value should be set to 1024. | SYS | OTHER | 1 |
| 30893 | With a running Open AT application, if the external application uses the AT+CMGS command to write an SMS, if the 0X0D character is used, then all the AT commands reply +CME ERROR: 515 | AT | SMS | 1 |
| 28769 | When a call is setup with a number having 'P' or 'p' modifier at the beginning (e.g. ATDPxxx), call fails with a CEER error cause 96. This does not allow to setup a call if 'P' or 'p' modifier is used. | AT | OTHER | 2 |
| 28977 | When an Open AT application is running, there is no way to enable the Wavecom Multiplexing protocol on the serial link (AT+WMUX=1 command has no effect). | AT | OTHER | 2 |
| 29515 | The module undergoes GPS cold reset when GPS hot reset is requested | AT | OTHER | 2 |
| 29828 | When concatenated commands AT+CPIN?;+CPINC? are given, the module gives +CME ERROR: 536 for +CPINC? and +CME ERROR: 515 for subsequent AT commands. Reboot is the only way to recover normal behavior. | AT | OTHER | 2 |
| 30125 | Class 1 SMS are always stored in ME even if the preferred storage area is set to SIM. | AT | SMS | 2 |
| 30162 | When AT+WBHV=1,1 is set, the module cannot be switched off using AT+CPOF command. | AT | OTHER | 2 |
| 30236 | During GCF test 27.22.5.2 §2.3, the SMS CB is not returned by the module. It should return a +CBM or +CBMI indication | AT | STK | 2 |
| 30237 | During GCF test 27.22.5.2 §2.3, the SMS CB is not returned by the module. It should return a +CBM or +CBMI indication | AT | STK | 2 |
| 30338 | GPO2 value switches from 0 to 1 when downloading via Xmodem | N/A | N/A | 2 |
| 30485 | On Q2501B, either ANTENNA_VOLT value or ADC_AUX value is wrong. | DEVICE | ADC/BAT | 2 |
| 30565 | PLMN list not updated with NAPRD10 2.6.8 and SE 22/08/2005 | AT | N/A | 2 |
| 30845 | AT+WGPSCONF=2 returns incorrect GPS temperature value. | DEVICE | ADC/BAT | 2 |
| 28984 | With a running Open AT application, if serial link configuration commands are concatenated with the AT&W one (E.g. AT+IFC=0,0;&W), the new configuration will not be stored in E2P memory. | AT | OTHER | 3 |
| 28611 28778 28902 29572 29773 29853 29940 30175 30502 30593 30651 30750 | User Guide updated | DOC | N/A | 3 |

6.2 Integrated But Not Validated Corrections/Improvement

None.

6.3 Specificities Versus Previous Official Release on the branch

| Description |
|--|
| V42bis compression – The number of dictionary entries is set to 1024 by default, instead of 2048 in previous OS (see also restriction applicable to A memories only). |

6.4 Certification Compliance

All the platforms are compliant to R&TTE EN 301 419-1 v4.1.1 and EN 301 511 v7.0.1.

The following table sums up the certifications passed for this software version or the last version that obtained a certificate.

| | GCF-CC / WM SW | PTCRB / WM SW |
|---------------|----------------|---------------|
| Q2400A | v3.18.0 / X51 | - |
| Q2406x | v3.18.0 / X51 | - |
| Q2426B | - | V3.2.1 / X51 |
| Q2501B | v3.18.0 / X51 | - |

6.5 Additional Information / Restrictions

This section lists additional information or restrictions that must be taken into account regarding the X.51a firmware.

6.5.1 Common to all modules

| Id | Description |
|-------|--|
| DF | TCP/IP Everywhere – The TCP/IP application is not activated by default. The AT+WOPEN=1 command has to be sent for TCP/IP stack activation. |
| 27784 | LD phonebook – When the module is reset, some of the Last Dialed Numbers might have been removed from the LD phonebook. |
| 28870 | Charge indications – Charge indications are not received on Q2501B. |
| 29282 | Downloader – It is no more possible to monitor the DCD signal (which is multiplexed with a GPIO) to launch automatic download. Indeed, the latest downloader to be used with X.51a version does not initialize GPIOs anymore. |
| 31086 | Battery charging - If BattLevelMax parameter is set to a higher value than 4490 with the command AT+WBCM, when the module restarts, the ADC values are no more available. The limit of BattLevelMax should be 5000. |

| | |
|-------|--|
| 31147 | SMS Status Report - When the SIM doesn't contain the EF-SMSR and Status Report is configured to be stored in flash (+CNMI and +CSMP commands), the Status Report received after sending a SMS (+CDSI indication) is not stored in flash and +CMGR command to read it blocks the module in +CME ERROR: 515 state. |
| 31223 | Certification – MANDATORY Test 27.22.4.7.1 seq 1.3 failed. |
| 31372 | Calling Line Identity Presentation - When an incoming call is made from a number which has been saved in the phonebook of the called party (ADN or ME), if the CLIP is activated on the called module and if the character set selected with the command AT+WPCS is "HEX" or "CUSTOM", a "@" character is added at the end of the name field. |
| 31385 | UART2 - Flow control does not work on UART2. |
| 31395 | Automatic dialing - AT%D1 command cannot be performed from FD (Fixed Dialing) directory. |
| 31678 | External application / Open AT application interaction - Reset ("Error #0011 : Release memory error...") may occur when at the same time an Open AT application treats received SMS and an external application sends AT commands to the module. |

6.5.2 Specific to A memories


| Id | Description |
|----------------|---|
| 28778 28757 | DATA CSD / GPRS – Data CSD calls and GPRS sessions are not simultaneously available. |
| 28844 | Agenda – A reset can occur during GPRS attachment when agenda events are stored. Consequently, agenda must not be used if the GPRS is used. |
| 31274 | TCP/IP Plug-in – On A memory module, reset may occur when using simultaneously or consecutively 2 TCP sockets, after having performed voice calls. |
| 31672 | V42bis compression – The number of dictionary entries is set to 1024 by default. This is also the maximum value that must be used with A memory modules. If an upper value is used and V42bis compression is enabled, the module may reset systematically when performing an outgoing DATA call. |

6.5.3 Specific to Q2501B module

| Id | Description |
|-------|---|
| DF | UART2 availability – The UART2 is not available when the GPS internal mode is activated on Q2501B (see AT+WMFM chapter in the AT Command Interface Guide). |
| 31391 | GPS – GPS UART speed cannot be changed using AT+WGPSCONF=1,<baudrate> command. This results in incorrect speed setting. |

6.5.4 Specific to M1306B modem

| Id | Description |
|-------|---|
| 31058 | GPIOs commands must not be used – M1306B modem does not respond after AT+WIOM=1023,1023 command. The only way to restore the modem is to re-download the X.51a software using DwlWin tool. |



wavecom 
Make it wireless

WAVECOM S.A. - 3 esplanade du Foncet - 92442 Issy-les-Moulineaux Cedex - France - Tel: +33(0)1 46 29 08 00 - Fax: +33(0)1 46 29 08 08
Wavecom, Inc. - 4810 Eastgate Mall - Second Floor - San Diego, CA 92121 - USA - Tel: +1 858 362 0101 - Fax: +1 858 558 5485
WAVECOM Asia Pacific Ltd. - 4/F, Shui On Centre - 6/8 Harbour Road - Hong Kong - Tel: +852 2824 0254 - Fax: +852 2824 025

www.wavecom.com