


CHANGE C13 TO 0,22 ON 600

DELETE ON 250, 400

DELETE ON 250

DELETE ON 250

DELETE ON 250, 400



ACFAIL

SHUTDOWN

ACFAIL

ALARMOSC

ACFAIL

SHUTDOWN

ALARM DISABLE

TEST/ALARM DISABLE RETURN

LOW BAT WARNING  
OPEN - 2 MIN  
CLOSED - 5 MIN

ALARMOSC

CLAMP

COMP

INVDISBL

J14 CC LOW BATTERY

J14 OC AC FAIL

J14 CC AC FAIL

J14 DB-9 GROUND

J14 RS-232 AC FAIL

J14 UPS SHUTDOWN

J14 DB-9 GROUND

